




## How can I correct the “Error occurred at RES\_DBDataSaving.vi”?



This error might appear with [Parseq](#) software and indicates an issue occurred when the test bench was trying to complete the data saving of the tests results.

It might happen when electric power is unexpectedly cut or the file Results.mdb is opened while a test is in progress.

To recover from this error you should retrieve a back-up copy of Results.mdb file knowing that the corrupted files should contain more updated test results that you might wish to recover.

Contact [Microplan Support](#) in case you further support.

### Lessons learned:

- Regular back-up of designated files is a good practice ([read more](#))
- The installation of a UPS device might prevent problems when electric power is unexpectedly cut
- It is advised to set up automatic routines, developed by Microplan team, to automatically transfer tests results from the PC of the test benches to company server.
- It is not advised to manipulate the database of test results Results.mdb while test bench is operational.